


*GVT/PGVT*  
*600x1200 mm*


[www.marazentiles.com](http://www.marazentiles.com)

CIDER ORANGE






COLONY BLUE




DARK BLACK






DARK CHOCOLATE





DIM GREY






LIGHT GREY



DOVER\_WHITE





LATTE IVORY




NEW DARK GREY





NOVEL TAN





PICCE CORE






POST WAR WHITE






ROSE\_HORK





SAND DAN





**SANDY LANE**






**SLATE GREY**





**STEELGREY**





**PLAIN WHITE MATT**

## Technical Details

Comparison of Indian Standard,ISO Standard

NO.	ITEM	INDIAN INDEX	ISO INDEX	TILES
01	Water absorption (%)	Average Value $\leq 0.5$	Average Value $\leq 0.5$	$\leq 0.08$
02	Breaking Strength (N)	Average Value $\geq 600$	Average Value $\geq 560$	600
03	Modulus of Rupture (MPa)	$\geq 35$	$\geq 35$	40
04	Abrasive Resistance	$\geq$ Grade 3	-	Grade 4
05	Resistance of thermal shock	Without Cracking and spalling after test	Without Cracking and spalling after test	Without Cracking and spalling
06	Resistance of crazing	Without Cracking and spalling after test	Without Cracking and spalling after test	Without Cracking and spalling after test
07	Frost Resistance	Without Cracking and spalling after test	Without Cracking and spalling after test	Without Cracking and spalling
08	Chemical Resistance	Not Lower than grade GB	Not Lower than grade GB	Grade GA
09	Stain Resistance	Not Lower than grade III	Not Lower than grade III	Grade 5
10	Limit of Radioactive Nuclear	Type A Ira $\leq 1.0$ IY $\leq 1.03$	-	Type A Ira $\leq 0.40$ IY $\leq 0.89$
11	Elastic limit (mm)	$\geq 12$	-	20
12	Anti-slip slope	$\geq 12^\circ$	-	$25^\circ$

Comparison of INDIAN Standard

rd

NO.	ITEM	INDIAN INDEX	ISO INDEX	TILES	
01	Size and bias (mm)	Length	$\pm 1.0$	$\pm 0.6$	$-1.0 \text{ --} 0.5$
		Width	$\pm 1.0$	$\pm 0.6$	$-0.28 \text{ --} +0.65$
		Thickness	$\pm 0.3$	-	$-0.08 \text{ --} +0.09$
		Average Thickness	$\leq 6.0$	-	$-4.72 \text{ --} 0.86$
		Length difference of opposite side	$\leq 1.0$	-	0.8
		Length difference of opposite angles	$\leq 1.5$	-	1.0
02	Surface Quality	-	At least 95% of plate; no obvious defects in its main area.	-	no obvious defects